


Inspection Summary



Executive Summary

Executive Summary: CCTV Drainage Inspection Report for St Joseph's College

Overall Condition Assessment

Our recent post blockage clearance CCTV drainage inspection at St Joseph's College, Lower Classroom Building has revealed a concerning number of defects, with a total of 12 issues identified across the 3 lateral branches serving the toilets. This assessment highlights the importance of proactive maintenance to prevent potential disruptions to the college's operations.

