

Recommendations

OTHER RECOMMENDATIONS

medium priority Short Term

Section 1 MH1 B1 to Toilet

Further root ingress removal and the installation of a 3 meter 100mm diameter resin impregnated drain lining is recommended to restore the structural integrity of the clay ware underground drain and also prevent future root ingress.

medium priority Short Term

Section 3 MH1 B3 to Toilet

Further root ingress removal and the installation of a 1 meter 100mm diameter resin impregnated drain lining is recommended to restore the structural integrity of the clay ware underground drain and also prevent future root ingress.

medium priority Short Term

Section 2 MH1 B2 to Toilet

Excavation and replacement of a 1 meter in length section of underground drain is recommended to restore the structural integrity of this drain and alleviate root ingress and a lack of gradient due to a displaced joint.

Summary by Priority

3 medium

