

Upstream		Length: 4.6m		8 observations	
0.00m	Survey Start Point		▶ 0:00		
0.08m	Broken (pipe has visibly moved) Clock: 12-12	4	▶ 0:05		
0.08m	Roots Band: Tap	3	▶ 0:05		
0.29m	Crack Clock: 02 to 10 Band: Circumferential	1	▶ 0:09		
0.29m	Joint Displaced Band: Medium (pipe wall thickness visible)	3	▶ 0:10		
0.50m	Water Level Cross-sectional Loss: 15% Remarks: "Water holding in drain due to displaced joint"		▶ 0:13		
4.61m	Finish Node Point		▶ 0:46		

